CompTIA

Exam Questions 220-1101

CompTIA A+ Certification Exam: Core 1

NEW QUESTION 1
A department sends in a ticket to report a printer is not working. The responding technician sees paper stuck to the fuser, which is much hotter than normal. The (user was just installed a few weeks ago. as indicated by the service history. Which of the following should the technician do NEXT?

A. Disable the printer for repairs.
B. Install a printer roller kit.
C. Remove the paper and let the fuser cool down.
D. Replace the paper with thicker paper stock.

Answer: C

NEW QUESTION 2
A network technician has been tasked with creating a patch cable. The RJ45 connectors will not slay attached to the cable. Which of the following tools Is needed to fix this Issue?

A. Cable tester
B. Crimper
C. Punchdown tool
D. Loopback plug

Answer: B

Explanation:
A crimper is a tool that is used to crimp (attach) an RJ45 connector onto the end of a patch cable. The crimper applies pressure to the connector to make a permanent connection between the connector and the cable, ensuring that the connector will stay attached to the cable.
A cable tester is used to test the connectivity of a network cable. A punchdown tool is used to terminate network cables in a patch panel or keystone jack. A loopback plug is a diagnostic tool that is used to test network interfaces by simulating network traffic.

NEW QUESTION 3
A user wants a second monitor installed on a laptop. The VGA/DVI or HDMI cables have already been connected. Which of the following should the technician do to configure the laptop to show both screens?

A. Power cycle the laptop.
B. Plug in the monitor to the USB port.
C. Adjust the monitor display settings.
D. Power cycle the monitor.

Answer: C

NEW QUESTION 4
An end user discovered that the touch-screen features on a Windows device have stopped working. Which of the following should a technician check?

A. Performance monitor
B. Tablet/PC settings
C. System configuration
D. Display settings

Answer: D

NEW QUESTION 5
Which of the following types of devices MOST often uses a Thunderbolt cable?

A. Linux PC
B. Android mobile
C. Apple laptop
D. Chromebook

Answer: C

Explanation:
CompTIA study guide says Apple Devices use thunderbolt and lightning cables the most, but it is being implemented in Windows and Linux products.

NEW QUESTION 6
A company has a dot matrix printer that uses carbon paper. The company reports that the first page is printing too light, although the following pages are still legible. Which of the following MOST likely needs to be fixed?

A. The print drum is worn and loose causing the printing to be light in places
B. The ribbon is low on ink or missing and must be replaced to get proper output
C. The heating element has failed, and a new one needs to be installed for proper transfer
D. The wrong type of filement is loaded, preventing it from sticking correctly
E. The fuser assembly is not calibrated properly, causing it to impact the paper too hard

Answer: B

Explanation:

Dot Matrix printers do not use heat, they use a pin striking an inked ribbon (for the first copy, the subsequent copies are handled by the carbon paper)

NEW QUESTION 7
A technician is commissioning a workstation that is required to have mirrored storage, utilizing two 4TB drives that support one failure. Which of the following BEST meets these requirements?

A. RAID 0
B. RAID 1
C. RAID 5
D. RAID 10

Answer: B

NEW QUESTION 8
Which of the following would MOST likely be used to obtain electronic images of a large number of printed documents?

A. NFC device
B. ADF/flatbed scanner
C. Camera/webcam
D. QR scanner

Answer: B

NEW QUESTION 9
Recently, an organization received a number of spam emails that passed through the spam gateway. The emails contained generally the same information, but the sending domains were different. Which of the following solutions would BEST help mitigate the issue?

A. Updating the keyword filtering
B. Editing the sender policy framework
C. Contacting the gateway vendor
D. Verifying DMARC is enabled

Answer: D

Explanation:
DMARC (Domain-based Message Authentication, Reporting and Conformance) is an email authentication protocol. It is designed to give email domain owners the ability to protect their domain from unauthorized use, commonly known as email spoofing.

NEW QUESTION 10
Which of the following connectors can be plugged into a Thunderbolt 3 port on a laptop?

A. miniUSB
B. microUS3
C. USB-A
D. USB-C

Answer: C

Explanation:
Thunderbolt 3 is a USB-C port, so any device with a USB-C connector can be plugged into it. MiniUSB, microUSB and USB-A are not compatible with Thunderbolt 3.

NEW QUESTION 10
A technician is implementing a SOHO wireless solution with three access points. Which of the following actions would avoid high latency?

A. Enabling and configuring a 5GHz antenna
B. Configuring separate IP ranges
C. Enabling multiple SSIDs
D. Configuring all devices with different channels

Answer: B

NEW QUESTION 12
The Chief Executive Officer wants to ensure company data is stored in a manner that provides the company with complete control over how the data is managed. Which of the following is the BEST cloud deployment model for this request?

A. Community
B. Hybrid
C. Public
D. Private

Answer: D

NEW QUESTION 13
A customer is using a satellite internet connection that is experiencing slowness. A technician notices high latency while pinging, but the download test is

performing perfectly with very good download speeds. Which of the following represents the NEXT action the technician should perform?

A. Restart the modem and run an online internet connection and speed diagnostic tool.
B. Guide the customer on how to upgrade the internet plan with the provider in order to improve latency.
C. Explain to the customer this is not an issue; this situation is normal for this type of internet connection.
D. Replace the modem because it is not working correctly based on the test result.

Answer: A

NEW QUESTION 15
A technician wants to deploy a .msl package lo a corporate network. The technician needs to verily the application deployment will not affect other legacy applications on the end users' computers. Which of the following would the technician consider the MOST appropriate for this situation?

A. Virtual network
B. Application virtualization
C. Cross-platform virtualization
D. Virtual sandbox
E. Virtual desktop

Answer: A

NEW QUESTION 18
A user brings an older laptop to the help desk and reports issues with the keyboard. Upon inspection, the technician does not see any external damage but notices that many keystrokes da not register in a word processor. The laptop works fine when the technician tests it with an external keyboard. Which of the following actions would MOST likely resolve the issue?

A. Disable the sticky keys feature.
B. Clean the keyboard.
C. Reset the BIOS settings to default.
D. Charge the laptop.

Answer: C

NEW QUESTION 23
Which of the following describes metered utilization of cloud resources?

A. Resources provisioned instantly
B. Payments made only for resources that are used
C. Resources pooled to increase computing power
D. Implementation of rapid elasticity

Answer: B

NEW QUESTION 28
A technician is working on a critical warehouse machine that will not turn on. The technician has determined the power supply for the machine failed. The warehouse manager is looking for a solution that will prevent downtime in the future. Which of the following devices should the technician install to meet this requirement?

A. Grounded power supply
B. Modular power supply
C. 220V power supply
D. Redundant power supply

Answer: D

Explanation:
A redundant power supply is a device that provides two or more power supplies connected in parallel so that when one fails, the other one will take over to ensure continuous power. This is ideal for critical warehouse machines that require a reliable power source and are at risk of downtime in the event of a power failure. Installing a redundant power supply will help to reduce the chances of an unexpected power outage and keep the machine running.

NEW QUESTION 31
A user is installing a new display on a desktop computer that only has a single DVI port for video input and a single HDMI port tot video output Which of me following does the technician need to complete the setup?

A. DigitaMo-analog converter
B. A/v switcher
C. DisplayPort to HDMI adapter
D. DVI to HDMI cable

Answer: D

Explanation:
The technician will need to connect the DVI port on the computer to the new display's HDMI port. To do this, a DVI to HDMI cable will be needed. This type of cable will allow the computer's DVI video signal to be transmitted to the new display's HDMI port.
A digital-to-analog converter (DAC) is used to convert a digital signal to an analog signal. An A/V switcher is used to switch between multiple audio and video sources and display them on a single monitor or display. A DisplayPort to HDMI adapter is used to convert a DisplayPort signal to an HDMI signal, but it is not necessary in this scenario as the computer has a DVI port and not a DisplayPort.

NEW QUESTION 34
A user is researching hard drives to upgrade a PC and has decided to purchase a NVMe drive. Which of the following Should the user confirm are available on the PC before making the purchase? (Select TWO).

A. SATA
B. M.2
C. PCIe
D. SAS
E. SCSI
F. DRAM

Answer: BC

Explanation:
NVMe (Non-Volatile Memory Express) drives are high-speed solid-state drives that utilize the PCIe (Peripheral Component Interconnect Express) interface to connect to the motherboard. Before purchasing an NVMe drive, the user should confirm that the PC has an available M.2 slot for the drive and that the PC has a PCIe interface for the M.2 slot.
SATA (Serial ATA) is an older interface for hard drives and is not compatible with NVMe drives. SAS (Serial Attached SCSI) is a newer interface for hard drives and is typically used for enterprise-level storage systems.
SCSI (Small Computer System Interface) is a parallel interface for hard drives that is primarily used in high-end workstations and servers. DRAM (Dynamic Random Access Memory) is a type of memory commonly used in computers, but it is not relevant to the storage of data on a hard drive.

NEW QUESTION 35
Which of the following is a method that can be used to securely connect a remote user's laptop to a corporate server?

A. WAN
B. VPN
C. SSL
D. DHCP

Answer: B

NEW QUESTION 36
An organization maintains various record types, including health and criminal justice records. Which of the following cloud environments is the organization MOST likely to use to limit the attack surface?

A. Public
B. Hybrid
C. Community
D. Private

Answer: D

NEW QUESTION 41
Which of the following cables replaced the Apple 30-pin connector and is also reversible?

A. USB-C
B. Lightning
C. miniUSB
D. DisplayPort

Answer: B

Explanation:
Lightning Connector: Apple introduced this brand-new connector back in 2012. It is over 80% smaller than the 30-pin connector and is reversible.
https://www.cablewholesale.com/support/technical_articles/whats_your_port.php#:~:text=Lightning%20Connec

NEW QUESTION 43
A technician was called in to look at a user's PC. The user reported the PC was very sluggish. The HDD light on the PC was constantly on without blinking. The PC itself was slow receiving input and took a very long time to load the OS. The technician also noticed updates had failed. Which of the following is MOST likely the cause of these issues?

A. The hard disk drivers have been corrupted
B. The HDD cables need reseating.
C. A RAID disk failed.
D. The HDD has no free space.

Answer: A

NEW QUESTION 44
A technician recently discovered me root cause of an application error that several users have been experiencing. The technician updated the configurations on the affected machines and verified full functionality was restored for all users, which of the following actions should the technician perform NEXT?

A. Write a knowledge base article in the ticketing software to expedite future Incidents.
B. Submit a bug report to the developer of the application, along with the steps taken to resolve the Issue.
C. Work with the developer to proactively collect the application logs to identify future errors of this type.
D. Send an email communication to the company about the issue and the steps taken to resolve it.

Answer: A

Explanation:
CompTIA 6-Step Troubleshooting Process:
* 1. Identify the problem.
* 2. Establish a theory of probably cause. (Question the obvious)
* 3. Test the theory to determine cause.
* 4. Establish a plan of action to resolve the problem and implement the solution.
* 5. Verify full system functionality and if applicable implement preventative measures.
* 6. Document findings, actions, and outcomes.

NEW QUESTION 49
A technician identified an issue on a workstation, obtained details from the user, and made a backup of the system. Which of the following should the technician do NEXT?

A. Determine the next steps to resolve the issue and document it.
B. Design a plan of action to resolve the issue and implement the solution.
C. Document the findings, actions, and outcomes.
D. Establish a theory of probable cause, researching internally or externally as needed.

Answer: D

Explanation:
"Identify the problem. • Question user and identify user changes to computer.• Perform backups before making changes.• Inquire regarding environmental or infrastructure changes.• Review system and application logs. * 2. Establish a theory of probable cause (question the obvious and if necessary, conduct internal or external research based on symptoms)

NEW QUESTION 54
A technician needs to install a printer on the network. Which of the following must the technician configure? (Select THREE).

A. PCL
B. Dots per inch
C. Gateway
D. Subnet mask
E. MAC address
F. MB
G. IP address
H. Drivers

Answer: AEH

NEW QUESTION 57
An online retailer wants to save money and is considering migrating to the public cloud so peak is over. Which of the following BEST describes this aspect of cloud computing?

A. Rapid elasticity
B. Metered utilization
C. Shared resources
D. High availability

Answer: A

Explanation:
Rapid elasticity is only suitable for a domain whose resource requirements suddenly up and down for a specific time interval. Referring to the question the online retailer wants to migrate to public cloud services during peak season, then wants it to be removed "automatically" when the peak is over.

NEW QUESTION 60
An office manager reports that a printer is experiencing performance issues. Printouts are smudging when they are handled, and. recently, whenever the manager tries to print oversized documents, the paper jams before anything is printed on it.

A. Mastered
B. Not Mastered

Answer: A

Explanation:
A picture containing text, electronics, printer Description automatically generated

NEW QUESTION 65
Which of the following is a valid use for PaaS?

A. Off-site backups
B. An application development environment
C. A virtual server installation and configuration model
D. A web application for asset management

Answer: B

NEW QUESTION 67
A technician is diagnosing a workstation that shuts down unexpectedly during a butn-in test. Which of the following is the MOST likely cause for this symptom?

A. Faulty CMOS battery
B. OS update issue
C. Overheating
D. Faulty RAM

Answer: C

NEW QUESTION 71
A user failed to gain access to a building's entrance after security measures at the entrance were upgraded last week. The company implemented the 13.56MHz frequency short band, and users can now utilize their mobile devices to authenticate. Which of the following has to be enabled for the mobile device to authenticate?

A. Bluetooth
B. Biometrics
C. NFC
D. PIN

Answer: C

NEW QUESTION 75
A user is unable to plug a USB 3.0 device into a USB port. Upon inspection, a technician notices the USB 3.0 port appears to be slightly smaller than the other connections. Which of the following Is the MOST likely cause?

A. A foreign object Is stuck Inside the port
B. The cable connection utilized the wrong orientation.
C. The USB cable is physically damaged.
D. The USB port belongs to a different form factor.

Answer: D

Explanation:

USB 3.0 ports are slightly smaller than other USB connections, so if the port appears to be the wrong size, it is likely that the port belongs to a different form factor. This can be caused by a number of factors, such as the device being too old to support USB 3.0, or the device not having a USB 3.0 port in the first place.

NEW QUESTION 77
A salesperson is using a weather application on a mobile device. The application appears to be draining the device's battery very quickly. Which of the following is the BEST action for the salesperson to take in order to view weather forecasts while traveling?

A. Enable the GPS service to ensure accurate location detection.
B. Update the PRL when getting to a new location.
C. Configure less location checks using cellular location services,
D. use the offices' Wi-Fi IP addresses as the geolocation mechanism.

Answer: C

Explanation:
The best action for the salesperson to take in order to view weather forecasts while traveling and minimize the battery drain on their mobile device is to configure fewer location checks using cellular location services. This can be done by adjusting the settings for the weather application to limit how often it checks for updates and uses location services. This will help to conserve the battery on the device and keep the application from consuming too much power.

NEW QUESTION 79
A technician is setting up a device to use two-factor authentication. Which of the following meets this requirement?

A. Thumbprint/retinal scan
B. Password/password
C. Password/thumbprint
D. Password/PIN

Answer: C

NEW QUESTION 83
A startup company is outgrowing its current office space and is requiring employees to work remotely. The company must comply with government-enforced requirements to safeguard all aspects of data, so the IT department plans to maintain complete control over users' operating systems. Which of the following should the IT department implement?

A. VDI
B. IaaS
C. VPN
D. SaaS

Answer: A

NEW QUESTION 84
Which of the following concepts would be used by an online retailer to quickly add more web servers during peak sales times?

A. Community cloud
B. Rapid elasticity
C. High availability
D. Metered service

Answer: B

NEW QUESTION 88
A customer reports that access to the network fileshare has become much slower than usual, but local applications do not seem to have trouble. The technician checks the download bandwidth and finds no issues. Which of the following should the technician check NEXT?

A. Level of network utilization
B. Customer use of two-factor authentication
C. Amount of local drive space
D. RAID array drive health

Answer: A

NEW QUESTION 90
A user visits the desk to report that a smartphone takes more than a day to fully charge. The user has already tested multiple wall outlets and swapped the charging cable, but the results are the same. Which of the following should the technician do FIRST?

A. Verify the power rating of the charger.
B. Ensure all unnecessary connectivity features are disabled.
C. Check that all missing smartphone OS updates are applied.
D. Complete a factory reset of the phone

Answer: A

NEW QUESTION 93
A user on the marketing team uses various multimedia applications that consume a lot of memory. The user needs to install more RAM to run these applications

effectively. When the user opens the computer case, the user sees four slots in two sets of colors. Which of the following memory types is MOST likely required?

A. Dual-channel
B. Triple-channel
C. Single-channel
D. Quad-channel
E. Error correction code RAM

Answer: A

NEW QUESTION 96
A user requested upgrades to a company-issued laptop to increase its performance while working with a large database stored on drive C. Which of the following tasks should a systems administrator complete to BEST meet this goal? (Select TWO).

A. Configure RAID 1.
B. Install a hybrid drive.
C. Upgrade to 1GB NIC.
D. Increase the RAM.
E. Migrate to a SSD.
F. Upgrade the power supply.

Answer: BD

Explanation:
CompTIA covers it in page 97 of the comptia A+ complete study guide.

NEW QUESTION 98
A technician has set up a new conference room with a TV and a video soundbar. The technician wants to test the system with a conference call. During the test, the TV speaker produces sound, but the soundbar does not.
Which of the following is the MOST likely cause of the issue?

A. The volume on the TV needs to be turned up.
B. The conference call needs to be unmuted for audio.
C. An incorrect HDMI cable is being used.
D. The TV's HDMI-ARC port is not being use

Answer: D

Explanation:
HDMI-ARC (Audio Return Channel) is an HDMI connection that allows audio to be sent from the TV to an external sound system, such as a soundbar. If the TV's HDMI-ARC port is not being used, then the soundbar will not receive any audio from the TV and thus will not produce any sound. To resolve the issue, the technician should ensure that the TV's HDMI-ARC port is being used to connect the TV to the soundbar.

NEW QUESTION 99
Which of the following 802.11 standards supports both 5GHz and 2.4GHz channel frequencies?

A. 802.11a
B. 802.11c
C. 802.11b
D. 802.11g

Answer: B

NEW QUESTION 100
A technician recently received a written warning for causing a system-wide outage. The outage was a result of an unscheduled patch being manually pushed during production hours. Which of the following could have MOST likely prevented the technician from receiving the warning?

A. Following corporate procedures
B. Testing before deployment
C. Documenting the findings
D. Establishing a plan of action

Answer: A

Explanation:
Following corporate procedures would have been the most likely factor that could have prevented the technician from receiving the written warning. Following established procedures, such as change management, helps ensure that changes made to the production environment are thoroughly tested, approved, and implemented in a controlled and safe manner, reducing the risk of system-wide outages and other unintended consequences.

NEW QUESTION 101
A startup is looking to immediately expand its data center but does not have the personnel or space to manage everything internally. The organization has multiple small offices and remote users with large computational and storage-solution requirements. Funding is not an issue for the company. Which of the following can BEST accomplish the company's goals?

A. SaaS
B. IaaS
C. ISP
D. SON

Answer: B

NEW QUESTION 106
A technician just finished assembling a new PC for a client. Upon POST, the device presents an unspecified beep code and turns off automatically after five seconds. The technician double-checks the bill of materials for the new build and confirms all items have been installed. Which of the following should the technician do NEXT?

A. Ensure thermal paste is being used on the CPU.
B. Check to make sure that any video cards have auxiliary power cabling connected.
C. Verify the header panel connector is properly connected.
D. Spot-check that the I/O shield for the motherboard is properly installed.

Answer: C

Explanation:
The technician should verify the header panel connector is properly connected. A beep code is a diagnostic
tool used by motherboards to indicate issues with hardware components. This beep code may be indicating an issue with the connection between the motherboard and the case's header panel connector. This connector is responsible for providing power to the system and any connected peripherals. Therefore, the technician should verify the connection is secure and properly connected before attempting any other troubleshooting steps.

NEW QUESTION 109
A user entered a help desk ticket stating the latest calendar updates have not appeared on the user's corporate mobile device for several days, even though updates do appear on the user's laptop. Which of the following actions will MOST likely enable calendar alerts?

A. Checking that the ringer volume on the device is high enough to be audible
B. Ensuring the corporate password is saved correctly in the calendar application
C. Installing a third-party calendar application and synchronizing it with the corporate calendar
D. Remotely wiping the mobile device and reinstalling all applications

Answer: B

NEW QUESTION 110
A home user has purchased a subscription for a service that blocks malicious sites by preventing them from resolving correctly. Which of the following settings MOST likely needs to be changed on the user's router to enable this functionally?

A. DNS server
B. Port forwarding
C. Perimeter network
D. Universal PnP
E. DHCP server

Answer: A

NEW QUESTION 113
A user calls the help desk lot assistance configuring an Android phone with a new NFC-enabled speaker that will be used for an upcoming conference call. The user was unable to direct the phone's audio to the NFC speaker. Which of the following sequences should the help desk technician walk the customer through to accomplish this task?

A. Enable NFC on the speake
B. Ensure the speaker is less than 33ft (10m) from the Android phon
C. On the phone's Bluetooth settings menu for Connected Devices, select Pair New Devic
D. Tap to accept the connection to the speaker when the prompt is displayed on the phone's screen.
E. Enable NFC and Bluetooth on the Android phon
F. From the Android phone's Bluetooth settings menu for Connected Devices, select the Previously Connected Devices optio
G. Select a listed device that most closely matches the speake
H. Tap lo accept the connection lo the speaker when the prompt is displayed on the phone's screen.
I. Enable NFC and Bluetooth on the Android phon
J. Tap and hold the Android phone to the spot on the speaker where the NFC logo is displaye
K. Accept the connection to the speaker when the prompt is displayed on the phone's screen.
L. Enable Wi-Fi on the speake
M. Enable Wi-Fi on the Android phon
N. Tap and hold the Android phone to the spot on the speaker where the NFC logo is displaye
O. Accept the connection to the speaker when the prompt is displayed on the phone's screen.

Answer: A

NEW QUESTION 116
A user's laptop is running out of disk space and requires a new hard drive. The user wants to replace the existing hard drive with the fastest possible I TB HDD. A technician assesses the user's hardware and determines the connections that are available. Which of the following drive types should the technician recommend as the BEST choice?

A. 1TB NVMe SSD
B. 1TB flash drive
C. 1TB SATA SSD
D. 1TB SAS

Answer: A

Explanation:
The best choice for the user's laptop is a 1TB NVMe SSD. NVMe (Non-Volatile Memory Express) is a high-performance storage protocol designed specifically for solid-state drives (SSDs). It is significantly faster than SATA SSDs and SAS hard drives, making it ideal for users who need fast storage for their laptop. NVMe SSDs also have lower latency and higher bandwidth than traditional hard drives, making them well-suited for data-intensive tasks such as video editing, gaming, and running multiple applications simultaneously. Additionally, NVMe offers more reliable data reliability than traditional hard drives, and is less susceptible to performance degradation over time.

NEW QUESTION 117
A Microsoft Windows user is preparing to work in another country and needs to comply with corporate policy for data protection when copying files to portable media. Which of the following solutions would MOST likely satisfy this requirement?

A. A USB 3.1 flash drive with BitLocker to Go installed
B. An SD memory card with NTFS
C. An xD memory card with ext3
D. A portable hard drive with FAT32

Answer: A

NEW QUESTION 119
A technician is upgrading a legacy wireless router for a home user. After installing the new router and configuring the SSID to be the same, none of the devices will connect to the network. Which of the following should the technician check NEXT?

A. OHCP pool configuration
B. MAC filtering list
C. Wireless protocol settings
D. ONS servers

Answer: B

NEW QUESTION 123
A laptop has been returned for a screen repair. The owner insists the screen is broken, but occasionally a faded image is able to be seen in very bright settings on the desktop. Which of the following steps should the repair technician take FIRST?

A. Replace the graphics card.
B. Replace the screen, as the customer insists.
C. Recommend the usage of an external display instead.
D. Ensure the backlight is functioning as expected.

Answer: D

NEW QUESTION 126
Which of the following is the SAFEST way to replace RAM on a server that has a redundant power supply?

A. Unplug one power cable.
B. Verify the RAM temperature.
C. Utilize a grounding strap.
D. Replace the RAM while the server is running.

Answer: C

Explanation:
Utilizing a grounding strap is the safest way to replace RAM on a server that has a redundant power supply. This is because the grounding strap prevents electrostatic discharge (ESD) when handling the RAM, which can cause damage to the RAM and the server. Therefore, it is important to always use a grounding strap when handling RAM or other sensitive components.

NEW QUESTION 130
Which of the following is the MAXIMUM power PoE+ provides?

A. 15.4W
B. 30W
C. 60W
D. 95W

Answer: B

Explanation:
The earliest PoE switches from a few years ago generated 15 Watts per port (IEEE 802.3af). Today, most use the PoE+ standard (IEEE 802.3at), which generates up to 30 Watts per port. That's plenty for most devices that people want to connect

NEW QUESTION 133
......

Thank You for Trying Our Product

We offer two products:

1st - We have Practice Tests Software with Actual Exam Questions

2nd - Questons and Answers in PDF Format

220-1101 Practice Exam Features:

* 220-1101 Questions and Answers Updated Frequently

* 220-1101 Practice Questions Verified by Expert Senior Certified Staff

* 220-1101 Most Realistic Questions that Guarantee you a Pass on Your FirstTry

* 220-1101 Practice Test Questions in Multiple Choice Formats and Updatesfor 1 Year

100% Actual & Verified — Instant Download, Please Click
[Order The 220-1101 Practice Test Here](https://www.certshared.com/exam/220-1101/)